

Mercer


MERCER CERAMIC FIRECLAY SINKS

Instructions for knocking out a pre-punched tap hole

INSTRUCTIONS







Due to our policy of continual improvement, we reserve the right to change specifications without prior notice.

Tools required

Ref	Description
1	Sharp ended nail punch
2	Hammer
3	Pencil or marker

Notes

lack

It is highly recomended that safety goggles and gloves are worn when knocking through the tap hole.

Procedure

I. Identify the centre of the pre-punched hole that you wish to use. Mark the centre on the enamelled side (glazed surface) of the sink.

DO NOT try to knock out the hole from underneath (Fig.1).

- **2.** Place the sink in a well supported position.
- **3.** Take a sharp ended nail punch, placing the point onto the mark made. Using a hammer, strike firmly the top of the punch until the point has been broken through to the underside of the pre-punched hole (**Fig.2**).
- **4.** Carefully chip away the remaining material to gradually enlarge the tap hole until you have remove the entire pre-punched hole **(Fig.3)**.
- You should then find the tap mixer you intended to use, will fit the hole.

